



Figure A-1 - Emigrant Creek (left) and Mill Creek (right) watersheds



Figure A-2 – View of Mill Creek from Road





Figure A-3 – Downstream view of cross section A on ML01



Figure A-4 – Diversion on ML01





Figure A-5 – Pool near cross section B on ML02



Figure A-6 – Upstream view of downstream part of ML02





Figure A-7 – ML03 downstream view near midpoint of reach



Figure A-8 - Drying out of downstream section of ML03





Figure A-9 - LWD jam on ML04



Figure A-10 - Upstream view of ML04





Figure A-11 - LWD on EM01, downstream of cross section B



Figure A-12 - More LWD on EM01 near cross section B





Figure A-13 – Overview of EM02, looking upstream over meadow.



Figure A-14 - Cross section A on EM02, looking over meadow





Figure A-15 - Cattle crossing on EM02, upstream of cross section B



Figure A-16 – View upstream of EM02.





Figure A-17 - Downstream section of EM02.