



Figure B-1. – Upstream view of FR01. Large woody debris and pool upstream provide good fish habitat.



Figure B-2 – Upstream view of downstream end of FR02.



Figure B-3 – Upstream view of downstream end of sub-reach FR02a. Many small fish in pools in river right side channel.



Figure B-4 – Downstream view of upstream end of sub-reach FR02b.



Figure B-5 – Downstream view of mid-channel bar in sub-reach FR02b.



Figure B-6 – Upstream view of FR03.



Figure B-7 – Suitable fish cover in reach FR03.




Figure B-8 – Upstream view of upper portion of reach FR04.



Figure B-9 – Upstream view of lower portion of reach FR04.



Figure B-10 – Overview of lower portion of Miners Creek.



Figure B-11 – Upstream view of upper portion of Miners Creek.



Figure B-12 – Overview of French Creek watershed from USFS Rd 41N14.



Figure B-13 – Downstream view of Duke Lake Creek, tributary to French Creek, from USFS Rd 41N14.



Figure B-14 – Exposed road cut (USFS Rd 41N14) through decomposed granite in headwaters of French Creek.



Figure B-15 – Upstream view of Paynes Lake Creek, tributary to French Creek, from USFS Rd 41N14.





Figure B-16 – Heavy erosion onto USFS Rd 41N14 from logging skid trail cut through decomposed granite in upper French Creek watershed.